

UNITED STATES OF AMERICA
DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION

Air Agency Certificate

Number OPIR361L

This certificate is issued to

PTI INDUSTRIES INCORPORATED
whose business address is

2 PEERLESS WAY
ENFIELD, CONNECTICUT 06082

*upon finding that its organization complies in all respects
with the requirements of the Federal Aviation Regulations
relating to the establishment of an Air Agency, and is
empowered to operate an approved* REPAIR STATION

with the following ratings:

LIMITED - NON DESTRUCTIVE INSPECTION

LIMITED - ENGINE (JULY 24, 1998)

LIMITED - AIRFRAME (FEBRUARY 21, 2001)

LIMITED ACCESSORY - MECHANICAL (MARCH 28, 2002)


*This certificate, unless canceled, suspended, or revoked,
shall continue in effect* INDEFINITELY.

Date issued:

FEBRUARY 22, 1996

REVISED: NOVEMBER 4, 2004

**This Certificate is not Transferable, and ANY MAJOR CHANGE IN THE BASIC FACILITIES, OR IN THE LOCATION THEREOF,
SHALL BE IMMEDIATELY REPORTED TO THE APPROPRIATE REGIONAL OFFICE OF THE FEDERAL AVIATION ADMINISTRATION**

By direction of the Administrator

KENNETH D. ROACH

MANAGER, NE-FSDO-03

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

A003. Ratings and Limitations

HQ Control: 01/30/04

HQ Revision: 010

The Certificate Holder is authorized the following Ratings and/or Limitations:

Class Ratings

None Authorized

Limited Ratings

<u>Rating</u>	<u>Manufacturer</u>	<u>Make / Model</u>	<u>Limitations</u>
Airframe	Boeing	B-777 Series	Cleaning only, Hamilton Sundstrand Condenser Reheater Heat Exchanger in accordance with Hamilton Sundstrand CMM 810210 as revised, section 21-72-02 repair SK1000059 as revised, accomplish note 3 steps A through J only.
		B-767-400 and B-767-400ER	Cleaning only, Hamilton Sundstrand Condenser Reheater Heat Exchanger in accordance with Hamilton Sundstrand CMM 825210 as revised, section 21-51-81 repair SK1000088 as revised accomplish note 2 steps A thru J only.
	Sikorsky	All Makes/All Models	Stripping of Coatings and Finishings Cleaning of metal parts Dichromate Treatment, Type III (Dow 7) and Chromic Acid Cleaning, Type VI (Dow 19).
	Kaman	K-1200 Series	Dichromate Treatment, Type III (Dow 7) and Chromic Acid Cleaning, Type VI (Dow 19) of the Transmission Center and End Housing.

Limited Ratings

<u>Rating</u>	<u>Manufacturer</u>	<u>Make / Model</u>	<u>Limitations</u>
Powerplant	General Electric	CF-34 Series	Compressor Stator Assembly Stages 1 and 2 Variable Vane Shrouds, Inspection and Cleaning in accordance with CF-34 Engine Manual Section 72-32-00. Compressor Stator Assembly Stages 1 and 2 Variable Vane Shrouds, Teflon Seal Relacement in accordance with CF-34 Engine Manual Section 72-32-00, Repair 08
		All Models	Perform cleaning to all models of GEAE, IAW Standard Practices Manual GEK 108792 Tasks: 70-21-02-110-002 Method 2 Vapor Degreasing 70-21-04-120-E01 Method 4 Dry Abrasive Blast 70-21-14-110-012 Method 14 Manually Assisted Detergent Cleaning 70-21-22-110-042 Method 22 Light duty Aqueous Cleaning - Method 1 70-21-23-110-053 Method 23 Hand Wipe Degreasing
	Pratt and Whitney	JT3D-7	Repair of Main Oil Pump assembly in accordance with Pratt and Whitney JT3D-7 Overhaul Manual section 72-61-5, repair 8, sections A1 thru A7
		All Models	Application of Antiseize, Antigalling Compound
		All Models	Abrasive Blast
		All Models	Cleaning of Metal Parts
Accessory - Mechanical	Hamilton Standard	All Models	Passive Treatment
Nondestructive Inspection, Testing, and Processing	All Makes/ All Models	All Models/ AllModels	Magnetic Particle Inspection
	All Makes/ AllModels	All Models/ All Models	Flourescent Penetrant Inspection

Limited Ratings - Specialized Services

<u>Rating</u>	<u>Specifications</u>	<u>Limitations</u>
None Authorized.		